


Fig. 1

Q

Q



26




Fig. 3






Fig. 4




Fig. 5




Fig. 6




Fig. 7




Fig. 8








Fig. 9








Fig. 12




Fig. 13




Fig. 14





Fig. 15








Fig. 17






Fig. 18



SINGLE PALLET CONFIGURATION

FIG. 19

(A)





DOUBLE PALLET CONFIGURATION


FIG 20


11

SIDE TELESCOPES TO RIQUIRED LENGTH














SIDE TELESCOPES TO REQUIRED LENGTH



CORNER PIECE SNAPS INTO SIDE PIECES

F16826

(C)



300

371

302

360

362

P1651

E




FIG 27




FIG 28





FIG 29 210

202

FIG 30

200

C/C







FIG 31










FIG 33



F1634



202

F1635

222

224

202

F1636

200


230



202


200

224

F1637














FIG 4D

206 204 F16 41  
202



206

FIG 42








FIG 43



51644

FIG 45

3.2



F1646





FIG 4





F1648

347

312





FIG 49



09/30/2003

15:12

SAFE STRAP 973-575-8424 → 12123820888

NO. 641

002

SEP-30-2003 14:33 FROM: BOB SHELTON

978 464 5044

TO: 19735758424

P.3

(A)





FIG 52 A

09/30/2003

15:12

SAFE STRAP 973-575-8424 → 12123820888

NO.641

003


SEP-30-2003 14:33 FROM:BOB SHELTON


978 464 5044

TO:19735758424


P.4

(A)





B



09/30/2003

15:12

SAFE STRAP 973-575-8424 → 12123820888

NO.641

006

SEP-30-2003 14:33 FROM:BOB SHELTON

978 464 5044

TO:19735758424

P.4

(B)




Fig 52F

09/30/2003

15:12

SAFE STRAP 973-575-8424 → 12123820888

NO. 641


007

SEP-30-2003 14:32 FROM: BOB SHELTON

978 464 5044

TO: 19735758424

P.2



(B)

FIG 52F








FIG 52-G

SEP-30-2003 14:33 FROM:BOB SHELTON

978 464 5044

TO:19735758424

P.4





FIG 52H

09/30/2003

15:12

SAFE STRAP 973-575-8424 → 12123820888

NO. 641

D10

SEP-30-2003 14:32 FROM: BOB SHELTON

978 464 5044

TO: 19735758424

P. 2




Fig 91H

**THIS PAGE IS INSERTED BY OIPE SCANNING  
AND IS NOT PART OF THE OFFICIAL RECORD**

**Best Available Images**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

**BLACK BORDERS**

**TEXT CUT OFF AT TOP, BOTTOM OR SIDES**

**FADED TEXT**

**BLURRY OR ILLEGIBLE TEXT**

**SKEWED/SLANTED IMAGES**

**COLORED PHOTOS HAVE BEEN RENDERED INTO BLACK AND WHITE**

**VERY DARK BLACK AND WHITE PHOTOS ✓**

**UNDECIPHERABLE GRAY SCALE DOCUMENTS**

**IMAGES ARE THE BEST AVAILABLE  
COPY. AS RESCANNING *WILL NOT*  
CORRECT IMAGES, PLEASE DO NOT  
REPORT THE IMAGES TO THE  
PROBLEM IMAGE BOX.**